

FSN Ref: 2026-FSN-0000143

FSCA Ref: 2026-FA-0000143

Date: 2026-06-30

URGENT Field Safety Notice
Introducer for Impella (sold within Impella Pump Sets and
Individually Packaged)

For Attention of*: Users of Introducer for Impella (sold within Impella Pump Sets and Individually Packaged)

Contact details of local representative (name, e-mail, telephone, address etc.) *

Abiomed Europe GmbH
Neuenhofer Weg 3
D-52074 Aachen
E-Mail: DL-EUFSCA@its.jnj.com
Malte Flory Tel. +49 172 455 68 57
Customer Service Tel.: +800 0 22 466 33

FSN Ref: 2026-FSN-0000143

FSCA Ref: 2026-FA-0000143

URGENT Field Safety Notice (FSN)

Risk of Introducer Hub Leakage

1. Information on Affected Devices*																																								
1.	1. Device Type(s)*																																							
	Introducer kit																																							
1.	2. Commercial name(s)*																																							
	Abiomed Impella 14 Fr Introducer Kit, Abiomed Impella 23 Fr Introducer Kit																																							
1.	3. Primary clinical purpose of device(s)*																																							
	The Introducer is intended for introduction of Impella catheters, in particular the Impella CP heart pump, into the body. The introducer supports the insertion procedure of the heart pump via the peripheral artery. The duration of use of the introducer is limited to the end of the insertion procedure or before moving the patient from the Cath Lab into ICU (if required). The intended use of the guide wire is limited to support the introduction of the Introducer Kit components (dilators and introducers).																																							
1.	4. Device Model/Catalogue/part number(s)*																																							
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;">Model number</th> <th style="width: 20%;">Catalogue number</th> <th style="width: 40%;">Product Name</th> <th style="width: 20%;">Manufacturer</th> </tr> </thead> <tbody> <tr> <td>0052-3046</td> <td>0048-0014</td> <td>Impella CP Smart Assist Set</td> <td>Abiomed</td> </tr> <tr> <td>0052-3052</td> <td>0052-0038</td> <td>ABMD Introducer Kit, 14Fr x Short</td> <td>Abiomed</td> </tr> <tr> <td>0052-3053</td> <td>0052-0039</td> <td>ABMD Introducer Kit, 14Fr x Long</td> <td>Abiomed</td> </tr> <tr> <td>0052-3006</td> <td>1000482</td> <td>Impella 5.5 with SmartAssist S2 Set</td> <td>Oscor</td> </tr> <tr> <td>0052-3021</td> <td>0046-0011</td> <td>Impella RP Pump Set</td> <td>Oscor</td> </tr> <tr> <td>0052-3021</td> <td>0052-0002-EU</td> <td>Introducer Kit, 23F</td> <td>Oscor</td> </tr> <tr> <td>0052-3006</td> <td>0052-0011-EU</td> <td>Axillary Insertion Kit</td> <td>Oscor</td> </tr> <tr> <td>0052-3006</td> <td>0550-0002</td> <td>Impella 5.5 with SmartAssist Set</td> <td>Oscor</td> </tr> </tbody> </table>				Model number	Catalogue number	Product Name	Manufacturer	0052-3046	0048-0014	Impella CP Smart Assist Set	Abiomed	0052-3052	0052-0038	ABMD Introducer Kit, 14Fr x Short	Abiomed	0052-3053	0052-0039	ABMD Introducer Kit, 14Fr x Long	Abiomed	0052-3006	1000482	Impella 5.5 with SmartAssist S2 Set	Oscor	0052-3021	0046-0011	Impella RP Pump Set	Oscor	0052-3021	0052-0002-EU	Introducer Kit, 23F	Oscor	0052-3006	0052-0011-EU	Axillary Insertion Kit	Oscor	0052-3006	0550-0002	Impella 5.5 with SmartAssist Set	Oscor
Model number	Catalogue number	Product Name	Manufacturer																																					
0052-3046	0048-0014	Impella CP Smart Assist Set	Abiomed																																					
0052-3052	0052-0038	ABMD Introducer Kit, 14Fr x Short	Abiomed																																					
0052-3053	0052-0039	ABMD Introducer Kit, 14Fr x Long	Abiomed																																					
0052-3006	1000482	Impella 5.5 with SmartAssist S2 Set	Oscor																																					
0052-3021	0046-0011	Impella RP Pump Set	Oscor																																					
0052-3021	0052-0002-EU	Introducer Kit, 23F	Oscor																																					
0052-3006	0052-0011-EU	Axillary Insertion Kit	Oscor																																					
0052-3006	0550-0002	Impella 5.5 with SmartAssist Set	Oscor																																					
1.	5. Software version																																							
	N/A																																							
1.	6. Affected serial or lot number range																																							
	All Impella Introducer Kits in the field distributed in Pump sets or as an independent item																																							
1.	7. Associated devices																																							
	Impella CP Smart Assist Set, Impella 5.5 with SmartAssist Set Impella RP Pump Set Axillary Insertion Kit Introducer Kit for Impella																																							
2. Reason for Field Safety Corrective Action (FSCA)*																																								
2.	1. Description of the product problem*																																							
	Abiomed has identified a potential for 14 and 23 Fr introducer sheath leakage from the sidearm, under the sheath cap and along the hub score lines in the hub region. The																																							


FSN Ref: 2026-FSN-0000143

FSCA Ref: 2026-FA-0000143

unexpected leakage in these specified locations is due to certain manufacturing related issues, which increase the risk of access-site bleeding. Abiomed, in collaboration with its manufacturing partner (Oscor), has initiated containment, correction, and corrective/preventative action activities to address the issue.

If this issue were to occur, the user would see blood loss at the sidearm and hub of the introducer sheath as shown below on the 14Fr introducers. Leak locations are the same for both 14Fr and 23Fr introducers.

Areas where users may see blood loss from the sidearm and hub region:



Abiomed, in collaboration with its manufacturing partner (Oscor), has implemented additional manufacturing controls and inspection measures to mitigate the identified leakage condition for future lots that are distributed. These additional controls and inspection measures do not apply to current lots in the field. In parallel, a comprehensive investigation is underway to determine root cause and to evaluate additional potential longer-term improvements to manufacturing processes and product design.

ACTIONS TO BE TAKEN BY CUSTOMER/USER:

- Product removal is not required, and hospitals may continue to use existing inventory. Physicians should continue follow the IFU, use appropriate clinical awareness, monitoring, and patient support as needed. Consider a device exchange or using the repositioning sheath to minimize blood loss if potential leakage from the sidearm and under the sheath cap and along the hub score lines in the hub region is observed.
- Review the information within this letter, complete all mandatory fields, sign, and return the Customer Reply Form to DL-EUFSCA@its.inj.com.
- Forward this notice to anyone in your facility that needs to be informed (i.e., those who manage, transport, store, stock, or use the subject products).
- If any of the subject products have been forwarded to another facility, contact that facility and provide them with this notice.
- Post a copy of this notice in a visible area for awareness.

FSN Ref: 2026-FSN-0000143

FSCA Ref: 2026-FA-0000143

	As with any medical device, adverse reactions or quality problems experienced with the use of this product should be reported to the manufacturer and/or the relevant Health Authority. At Abiomed, our priority is to our customers and their patients, and that includes the safe and effective use of our products. If you have questions or concerns regarding this notice, please contact DL-EUFSCA@its.jnj.com or your local clinical field staff. Thank you for your cooperation.
2.	2. Hazard giving rise to the FSCA* Introducer leakage may reasonably be expected to result in access site bleeding at the time of sheath insertion or early device manipulation. In certain instances, this would be expected to cause blood loss requiring medical intervention, such as device exchange or removal, manual compression, and, in some cases, blood transfusion. In certain rare circumstances, particularly patients undergoing large bore vascular access with systemic anticoagulation or limited physiologic reserve (with a bleed that went undetected), exposure to this hazard may result in life-threatening hemorrhage and hemodynamic instability which may lead to an outcome of death.
2.	3. Probability of problem arising A review of global Abiomed complaints from February 1, 2023 to April 22, 2026 found Introducer leaking in 0.05% of cases (76 complaints reported).
2.	4. Predicted risk to patient/users The complaints review determined that no patient deaths are attributable to the issue under investigation. However, three complaints have corresponding MDRs reporting patient deaths. Abiomed has received eight reports of major bleeding which is a serious injury and have been reported as such.
2.	5. Further information to help characterise the problem No further information
2.	6. Background on Issue This potential issue was detected during Abiomed internal retrospective review of complaints.
2.	7. Other information relevant to FSCA N/A

3. Type of Action to mitigate the risk*

3.	1. Action To Be Taken by the User* ☒ Identify Device ☐ Quarantine Device ☐ Return Device ☐ Destroy Device ☐ On-site device modification / inspection ☒ Follow patient management recommendations. ☒ Take note of amendment / reinforcement of Instructions for Use (IFU) ☐ Other ☐ None
----	--

FSN Ref: 2026-FSN-0000143

FSCA Ref: 2026-FA-0000143

Follow recommendations described in section 2.1 ACTIONS TO BE TAKEN BY CUSTOMER/USER: - Product removal is not required, and hospitals may continue to use existing inventory. Physicians should continue to follow the IFU, use appropriate clinical awareness, monitoring, and patient support as needed. Consider a device exchange or using the repositioning sheath to minimize blood loss if potential leakage from the sidearm and under the sheath cap and along the hub score lines in the hub region is observed. - Review the information within this letter, complete all mandatory fields, sign, and return the Customer Reply Form to DL-EUFSCA@its.inj.com. - Forward this notice to anyone in your facility that needs to be informed (i.e., those who manage, transport, store, stock, or use the subject products). - If any of the subject products have been forwarded to another facility, contact that facility and provide them with this notice. - Post a copy of this notice in a visible area for awareness. - As with any medical device, adverse reactions or quality problems experienced with the use of this product should be reported to the manufacturer and/or the relevant Health Authority.		
3.	2. By when the action should be completed?	Upon awareness
3.	3. Is customer Reply Required? * (If yes, form attached specifying deadline for return)	Yes
3.	4. Action Being Taken by the Manufacturer* ☐ Product Removal ☐ Software upgrade ☒ Other ☐ On-site device modification/inspection ☐ IFU or labelling change ☐ None Abiomed, in collaboration with its manufacturing partner (Oscor), has implemented additional manufacturing controls and inspection measures to mitigate the identified leakage condition for future lots that are distributed. A Corrective and Preventive Action (CAPA) has been initiated to document investigation into the root cause and manage any corrective actions.	
3.	5. By when the action should be completed?	Abiomed is investigating and implementing appropriate corrective actions. The timeline is being established.
3.	6. Is the FSN required to be communicated to the patient /lay user?	No

FSN Ref: 2026-FSN-0000143

FSCA Ref: 2026-FA-0000143

4. General Information*		
4.	1. FSN Type*	New
4.	2. For updated FSN, reference number and date of previous FSN	N/A
4.	3. For Updated FSN, key new information as follows:	
	N/A	
4.	4. Further advice or information already expected in follow-up FSN? *	No
4.	5. If follow-up FSN expected, what is the further advice expected to relate to:	
	N/A	
4.	6. Anticipated timescale for follow-up FSN	N/A
4.	7. Manufacturer information (For contact details of local representative refer to page 1 of this FSN)	
	a. Company Name (1)	Abiomed Inc.
	b. Address (1)	22 Cherry Hill Drive, Danvers, MA, US
	c. Website address (1)	www.heartrecovery.com
	d. Company Name (2)	Oscor Inc.
	e. Address (2)	4875 Palm Harbor Blvd., 34683, Palm Harbor, US
	f. Website address (2)	www.integer.net
4.	8. The Competent (Regulatory) Authority of your country has been informed about this communication to customers.	
4.	9. List of attachments/appendices:	None
4.	10. Name	Malte Flory Commercial Quality Sr Manager EMEA

Transmission of this Field Safety Notice	
	This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where Impella Introducer Kits have been transferred. Please transfer this notice to other organisations on which this action has an impact. (As appropriate) Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action and keep this FSN together with the existing version of the product IFU. Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback. *

FSN Ref: 2026-FSN-0000143 FSCA Ref: 2026-FA-0000143

URGENT Field Safety Notice (FSN)
Introducer for Impella

Customer Reply Form

Mandatory fields are marked with *

1. Field Safety Notice (FSN) information	
FSN Reference number*	2026-FA-0000143
FSN Date*	30-06-2026
Product/ Device name*	Abiomed Impella 14 Fr Introducer Kit, Abiomed Impella 23 Fr Introducer Kit
Product Code(s) Catalogue number (Model number)	0048-0014 (0052-3046) 0052-0038 (0052-3052) 0052-0039 (0052-3053) 1000482 (0052-3006) 0046-0011 (0052-3021) 0052-0002-EU (0052-3021) 0052-0011-EU (0052-3006) 0550-0002 (0052-3006)

2. Customer Details	
Account Number	
Healthcare Organisation Name*	
Organisation Address*	
Department/Unit	
Shipping address if different to above	
Contact Name*	
Title or Function	
Telephone number*	
Email*	

3. Customer action undertaken on behalf of Healthcare Organisation		
☐	I confirm receipt of the Field Safety Notice and that I read and understood its content.*	Complete or enter N/A
☐	The Organisation has performed all actions requested by the FSN.*	Complete or enter N/A
☐	The information and required actions have been brought to the attention of all relevant users.*	Complete or enter N/A
☐	I have a query please contact me	Enter contact details if different from above and brief description of query
Print Name*		
Signature*		
Date*		

FSN Ref: 2026-FSN-0000143 **FSCA Ref:** 2026-FA-0000143

4. Return acknowledgement to sender	
Email	DL-EUFSCA@its.jnj.com
Customer Helpline	+800 0 22 466 33
Postal Address	Abiomed Europe GmbH Att. of Malte Flory Neuenhofer Weg 3 52074 Aachen -Germany
Web Portal	www.abiomed.eu ; www.heartrecovery.eu
Deadline for returning the customer reply form*	Please return within 7 working days

It is important that your organisation takes the actions detailed in the FSN and confirms that you have received the FSN.

Your organisation's reply is the evidence we need to monitor the progress of the corrective actions.