

08.05.2025

## URGENT SAFETY INFORMATION

**Action:** Product recall

**Products concerned:** CarpoFit® monoblock broaches


**implantcast reference no.:** FSCA\_25001

Dear Sir or Madam,

By means of this urgent safety information we would like to advise you about a recall which has been voluntarily initiated by implantcast GmbH for the products listed below:

Item Description	REF Number	LOT Number <sup>1</sup>
CarpoFit® monoblock broach sz. 5 mm	00510945	n.a.
CarpoFit® monoblock broach sz. 6 mm	00510946	n.a.
CarpoFit® monoblock broach sz. 7 mm	00510947	n.a.
CarpoFit® monoblock broach sz. 8 mm	00510948	n.a.

It was noted that in the above-mentioned CarpoFit® monoblock rasps, a product fault may be possible with regard to the alignment of the rasp head. An excerpt from the technical drawing will illustrate this:



<sup>1</sup> The product recall concerns all products of the above-mentioned REF numbers. A limitation to individual lots is not possible.



As one can see in the picture, the rasp head shows a curve. In the defective products, the rasp head was rotated by 180° and welded onto the rasp handle. This defect pattern could be found in individual products of all sizes and could not be limited to specific lots. It should be mentioned that not all rasps show the product defect described.

You are being informed, as you have at least one instrument container on stock which might contain potentially defect CarpoFit® monoblock broaches.

The instrument containers in question are as follows:

Affected Instrument Container	REF Number
CarpoFit® – container	00519900
CarpoFit® container 1	00519901

Each instrument container contains all broach sizes (sizes 5 to 8)

#### Risk Assessment / Patient Aftercare:

All possible risks are detected intraoperatively. Therefore, a specific patient aftercare is not necessary.

implantcast GmbH knows no case, in which a patient was affected due to a faulty CarpoFit® monoblock broach.

Hazardous Situations		
	Most Probable Consequence	Most Serious Consequence
Description of <b>direct health consequences</b> that could result from the use of or exposure to the product in question.	<p>The fault in the rasps is detected intraoperatively <b>before</b> the rasping process:</p> <p>The faulty rasp may be turned by 180° and then used.  <b><u>No effect on the patient is to be expected.</u></b></p>	<p>The fault in the rasps is <b><u>not</u></b> detected before the rasping process:</p> <p>Preparation is performed using a faulty rasp. This <b><u>may</u></b> result <b><u>in a bone fissure or a tilting / incomplete impacting of the stem.</u></b></p> <p>Both will be noticed latest when trial positioning and stability testing is performed and will be corrected intraoperatively.</p>
	Most Probable Consequence	Most Serious Consequence
Description of <b>long-term health consequences</b> that could result from the use of or exposure to the product in question.	None	None

**Course of action to be conducted:**

1. Please read this safety information carefully and make sure all relevant departments and officeholders are informed about its content.
2. Please keep this safety information.
3. Please fill in the attached reply form and return it to implantcast GmbH within **five working days** via E-mail to [FSCA@implantcast.de](mailto:FSCA@implantcast.de).
4. Please return affected instrument container to implantcast GmbH.

The target date for completion of this action is **23.05.2025**. Your prompt response will enable us to meet this deadline and to ensure that all non-compliant products are removed from the market as soon as possible.


We confirm that the respective European National Competent Authorities have been notified about this urgent safety information according to MDR EU 2017/745.

On behalf of implantcast GmbH we would like to thank you for your help and support with the implementation of this measure and apologize for any inconvenience caused.


We would like to assure you that implantcast GmbH does all in its power to ensure that only such products are on the market that comply with your and our high standards of quality.

Should any questions arise, please contact our product manager for CarpoFit® system or our director sales and marketing.


**Product Manager**




**Director Sales and Marketing**



Sincerely yours



Leiter Marketing und Vertrieb



PRRC-Safety

Please return by e-mail to [FSCA@implantcast.de](mailto:FSCA@implantcast.de)

## Reply form urgent safety information

implantcast Referenz-No.: FSCA\_25001

Affected Instrument Container	REF Number	LOT Number
CarpoFit® – container	00519900	
CarpoFit® container 1	00519901	

### BY SIGNING YOU CONFIRM:

1. Having received the urgent safety information dated 08.05.2025 as well as having taken note of the received information.
2. That all instrument containers that contain possibly defective CarpoFit® monoblock broaches will be returned to the following address:

implantcast GmbH  
 AWS-Eingang  
 FSCA\_25001  
 Alter Postweg 10b  
 21614 Buxtehude

Please sign the reply form and return it by E-Mail to: [FSCA@implantcast.de](mailto:FSCA@implantcast.de).

Hospital and Address	
implantcast Customer Number	
Name of Contact Person	
Function of Contact Person	
Phone No. of Contact Person	
Date	Signature